


Stage 1: 0.1 K  
Stage 2: 0.1-0.5 K  
Stage 3: 0.5-1.2 K  
Stage 4: 1.2-4.0 K



0.1 K Cold Finger Mount Point

PIPER CADR Basics  
T. Essinger-Hileman

Dimensions in inches